

10/032,168
Probe Mark Inspection Method and Apparatus Wallack

Sheet 1 of 7





Figure 1

Sheet 2 of 7





10/032,168
Probe Mark Inspection Method and Apparatus
Wallack

Sheet 3 of 7




Figure 3




Figure 4





Figure 5

Merge Disconnected Regions

Return Probe Mark Characteristics and Quantification Data

420


440






10/032,168 Probe Mark Inspection Method and Apparatus Wallack

Sheet 6 of 7





10/032,168
Probe Mark Inspection Method and Apparatus
Wallack

Sheet 7 of 7




Figure 8




Figure 9